

From: [Garyg Miller](#)
To: [Dipanjana Bhattacharya](#)
Subject: Fw: Preliminary Data for Gulfco AST Tank Farm Containment Area Verification Soil Samples
Date: 01/27/2011 02:11 PM
Attachments: [Draft Fig-2 Former AST Tank Farm Verification Sample Locations.pdf](#)

Dipa - here is the sample location map for the stained soil samples below the Gulfco tanks.

Thanks,

Gary Miller, P.E.
Remediation Project Manager
EPA Region 6 - Superfund (6SF-RA)
(214) 665-8318
miller.garyg@epa.gov

----- Forwarded by Garyg Miller/R6/USEPA/US on 01/27/2011 02:06 PM -----

From: "Eric Pastor" <eric.pastor@pbwllc.com>
To: Garyg Miller/R6/USEPA/US@EPA
Cc: "Voskov, Luda" <LVOSKOV@tceq.state.tx.us>
Date: 01/26/2011 11:58 AM
Subject: RE: Preliminary Data for Gulfco AST Tank Farm Containment Area Verification Soil Samples

Hi Gary –

Attached is a draft figure that shows the soil sample locations.

Approximate sample depths were as follows:

North Containment Area

T-15-F: from base of scraped area approximately 0.8 ft. below containment area floor
T-21-F: from base of scraped area approximately 0.5 ft. below containment area floor
NC-0-0.3: from containment area floor surface to depth of 0.3 ft.
T-2-WEST: west wall of excavation, near southwest corner, 2.5 ft below containment area floor
T-6-FLOOR: floor of excavation, 5.8 ft below containment area floor
T-6-EAST: east wall of excavation, 4.0 ft below containment area floor
T-6-SOUTH: south wall of excavation, 4.5 ft below containment area floor
T-6-NORTH: north wall of excavation, 2.0 ft below containment area floor

South Containment Area



9543120

SC-W: clay surface at base of trench, 0.7 ft below top of concrete pad
SC-E: clay surface at base of trench, 0.7 ft below top of concrete pad

Please let me know if you have any questions – as I mentioned previously, we will provide these and additional descriptions/details in the removal action report.

Also, as we previously discussed, I will shortly be sending you a request for an extension to the deadline for completion of field activities to allow loading of the remaining roll-off boxes that are on-site pending assignment of disposal slots from Clean Harbors.

Thanks.

Eric Pastor
Pastor, Behling & Wheeler, LLC
2201 Double Creek Drive, Suite 4004
Round Rock, Texas 78664
512-671-3434

From: Eric Pastor
Sent: Thursday, January 20, 2011 4:21 PM
To: 'Miller.Garyg@epamail.epa.gov'
Cc: Voskov, Luda
Subject: RE: Preliminary Data for Gulfco AST Tank Farm Containment Area Verification Soil Samples

Hi Gary –

Will do. We are putting together a sample location map and more detailed table for inclusion in the removal action report.

Thanks.

Eric Pastor
Pastor, Behling & Wheeler, LLC
2201 Double Creek Drive, Suite 4004
Round Rock, Texas 78664

512-671-3434

From: Miller.Garyg@epamail.epa.gov [mailto:Miller.Garyg@epamail.epa.gov]
Sent: Thursday, January 20, 2011 4:18 PM
To: Eric Pastor
Cc: Voskov, Luda
Subject: Fw: Preliminary Data for Gulfco AST Tank Farm Containment Area Verification Soil Samples

Eric,

Please let us know the samples locations and depths for the verification samples.

Thanks,

Gary Miller, P.E.
Remediation Project Manager
EPA Region 6 - Superfund (6SF-RA)
(214) 665-8318



millер.garyg@epa.gov Draft Fig-2 Former AST Tank Farm Verification Sample Locations.pdf